

Location Information					Material Information											
Building #	Location	Floor	Rm	Functional Area	Type	Description	Quantity	Condition	Friable	Sample Taken	Removed	Asbestos Present	Estimated Abatement Cost	Samples	Exposure #	Next Inspection
101	Interior	1	n/a	Mechanical Room	Miscellaneous	Mineral Particulate / Rock Wool	1 other	Good	No	Yes	No	No		GM020020	NA	07/03/05 : TBD
102	Interior	1	101	N/A	Other	Mineral particulate & glass fibers		Poor	Yes	Yes	No	No		GM050021	NA	10/28/06 : TBD
102	Interior	1	112	West Wing	TSI	4 vertical pipes (Floor to Ceiling)	32 Linear Feet	Poor	Yes	No	Yes				NA	12/03/02 : Removed
102	Interior	1	131	N/A	TSI	2Elbows+2LF Ceiling Tiles	2 Linear Feet	Poor	Yes	No	Yes				NA	11/20/02 : Removed
102	Interior	1	143	North Bathroom 1st floor	Surfacing	(2nd ceiling Plaster on steel mesh)	1 other	Good	No	Yes	No	No		GM030067	NA	06/19/06 : TBD
102	Interior	1	148	N/A	Miscellaneous	Floor Tile & Mastic	440 Square Feet	Fair	No	No	Yes		\$2,200		NA	12/03/05 : Removed
102	Interior	1	151	Conference Room	Miscellaneous	Plaster-like foam ceiling tile	1 each	Good	No	Yes	No	No		GM020067	NA	12/05/05 : TBD
102	Interior	1	151	Conference Room	Miscellaneous	Plaster-like foam	1 each	Good	No	Yes	No	No		GM020066	NA	12/05/05 : TBD
102	Interior	1	151	Conference Room	Surfacing	Light colored floor tile	530 Square Feet	Good	No	Yes	Yes	Yes	\$450	GM030020	NA	01/31/06 : TBD
102	Interior	1	151	Conference Room	Surfacing	Black Floor tile	530 Square Feet	Good	No	Yes	Yes	Yes	\$1,450	GM030021	NA	01/31/06 : TBD
102	Interior	1	151	Conference Room	Surfacing	Mastic Scrapings	530 Square Feet	Good	No	Yes	Yes	Yes	\$1,450	GM030022	NA	01/31/06 : TBD
102	Interior	1	151	Conference Room	Surfacing	Floor tile w/mastic	530 Square Feet	Good	No	Yes	Yes	Yes	\$1,450	GM030023	NA	01/31/06 : TBD
102	Interior	1	153	HELP DESK	Miscellaneous	Floor Tile and Mastic Adhesives	400 Square Feet	Fair	Yes	Yes	Yes	Yes	\$1,390	GM050022 thru 25, GM050022 thru 25	NA	06/20/06 : TBD
102	Interior	1	154	N/A	Surfacing	Raised Floor Tile	1 other	Good	No	Yes	Yes	No		GM030061	NA	06/16/06 : TBD
102	Interior	1	N/A	Basement	TSI	Cover, insulation, pipe	20 Linear Feet	Good	No	No	Yes				24	11/06/04 : TBD
102	Interior	1	N/A	Basement	TSI	mastic on metal duct under wrap insulation	1874 Square Feet	Good	No	No	Yes				NA	09/01/05 : TBD
102	Interior	1	N/A	Basement	TSI	insulation, pipe, 10-inch dia.	1874 Square Feet	Good	Yes	Yes	Yes	No		0007981-55	24	11/06/02 : TBD
102	Interior	1	N/A	Basement	TSI	insulation, pipe, 12-inch dia.	1874 Square Feet	Good	Yes	Yes	Yes	No		007981-54	24	11/06/02 : TBD
102	Interior	1	N/A	Basement	TSI	Pipe Chase behind bathroom	262 Linear Feet	Good	No	No	Yes				NA	09/01/07 : TBD
102	Interior	1	N/A	Basement Stairwell	Miscellaneous	Tile, floor, dark gray, 9x9	9 Square Feet	Good	No	No	No				12	11/06/04 : TBD
102	Interior	1	N/A	Basement Stairwell	Miscellaneous	Tile, floor, gray, 9x9	9 Square Feet	Good	No	No	No				12	11/06/04 : TBD
102	Interior	1	N/A	Basement Stairwell	Miscellaneous	Tile, floor, black,	4 Square Feet	Good	No	No	Yes				6	11/06/04 : TBD
102	Interior	1	n/a	Records Storage Room	Miscellaneous	Tile, floor, brown, 9x9	450 Square Feet	Good	No	No	No				12	11/06/04 : TBD
102	Interior	1	n/a	Records Storage Room	TSI	Insulation, pipe		Good	Yes	Yes	No	No		GMARS11070 1-102-02	24	11/06/02 : TBD
102	Interior	1	n/a	South Wing Hallway	Surfacing	Wall Plaster	1 other	Good	No	Yes	No	No		GM030024	NA	02/13/06 : TBD
102	Interior	2	208	Comm.??	Surfacing	Carpet Adhesive	1 each	Good	No	Yes	No	No		GM030046	NA	05/28/06 : TBD
102	Interior	2	208	Communication	Other	Vinyl Floor Tile	1 each	Good	No	Yes	Yes	Yes		GM030047	NA	05/28/06 : TBD
102	Interior	2	208	Southeast corner???	Surfacing	Carpet Adhesive	1 other	Good	No	Yes	No	No		GM030045	NA	05/28/06 : TBD
102	Interior	2	208	Southeast corner???	Surfacing	Tile Adhesive 15%Chrysotile	118 Square Feet	Good	No	Yes	Yes	Yes		GM030044	NA	05/28/06 : TBD
102	Interior	2	208	Southeast corner???	Surfacing	Carpet Adhesive	1 each	Good	No	Yes	No	No		GM030043	NA	05/28/06 : TBD
102	Interior	2	215	N/A	Miscellaneous	Asbestos Tile & Adhesive	3 Square Feet	Fair	Yes	No	Yes		\$450		NA	02/04/04 : TBD
102	Interior	2	248	North Air Handling Mechanical Room	TSI	Pipe Insulation (Abandon Room)		Fair	Yes	No	Yes				NA	10/25/06 : TBD
102	Interior	2	249	South Air Handling Mechanical Room	TSI	Pipe Insulation		Fair	Yes	No	Yes				NA	10/25/06 : TBD
102	Interior	2	N/A	CENTER STAIRWAY (STEPS)	Miscellaneous	Vinyl Steps Covering and Mastic	160 Square Feet	Poor	Yes	No	Yes				NA	10/25/06 : TBD
102	Exterior	2	N/A	ROOF	Surfacing	Asphaltic Material / Mineral Particulate	1 other	Good	No	Yes	No	Yes		02829-102B	NA	09/03/05 : TBD
102	Exterior	2	N/A	ROOF	Surfacing	Asphaltic Material / Glass Wool / Mineral Particulate	1 other	Good	No	Yes	No	No		02829-102A	NA	09/03/05 : TBD
102	Exterior	2	N/A	Roof Utility Room	Miscellaneous	Glazing compound, window	60 Linear Feet	Good	No	Yes	Yes	No		GMARS11070 1-102-03	7	11/07/04 : TBD
102	Interior	Basement	N/A	NE Tunnel	TSI	Insulation +200 Fittings + Main Pipe Expan Joint Black Mastic/Insulation + 38 Rods	215 Linear Feet	Fair	Yes	No	Yes				NA	12/03/03 : TBD

102	Interior	Basement	N/A	SE Tunnel	TSI	200LF Pipe/Insulation +191 fittings+30Rods+24LFPaper Jacks+4Main pipe Ex Joint Mastic&Insulation	200 Linear Feet	Fair	Yes	No	Yes			NA	12/03/03 : TBD
102	Interior	Basement	N/A	SW Tunnel (Steam Pipes)	TSI	500LF Pipes+205Fittings+82Rods	500 Linear Feet	Poor	Yes	No	Yes			NA	10/25/06 : TBD
102	Interior	N/A	N/A	BASEMENT	TSI	Heat Exchanger Covering	1874 Square Feet	Good	Yes	Yes	No	0007981-52		NA	02/28/04 : TBD
102	Interior	N/A	N/A	BASEMENT	TSI	Hot Water Inlet	1874 Linear Feet	Good	No	Yes	No	0007981-53		NA	02/28/06 : TBD
104	Interior	1	104	N/A	Miscellaneous	12x12 floor tile	600 Square Feet	Good	No	No	No			6	11/06/04 : TBD
104	Interior	1	104	N/A	TSI	insulation, pipe and cover	30 Linear Feet	Good	Yes	No	No			10	11/06/02 : TBD
104	Interior	1	104	Office Spaces	Miscellaneous	Tile, floor, white, 12x12	160 Square Feet	Good	No	No	No			6	11/06/04 : TBD
104	Interior	1	107	N/A	Miscellaneous	12x12 floor tile	600 Square Feet	Good	No	No	No			6	11/06/04 : TBD
104	Interior	1	107	N/A	TSI	insulation, pipe and cover	30 Linear Feet	Good	Yes	No	No			10	11/06/02 : TBD
104	Interior	1	107	Office Spaces	Miscellaneous	Tile, floor, white, 12x12	160 Square Feet	Good	No	No	No			6	11/06/04 : TBD
104	Interior	1	116	Vehicle Operations Office	Miscellaneous	Tile, floor, beige, 12x12	80 Square Feet	Good	No	No	No			6	11/06/04 : TBD
104	Interior	1	n/a	Mechanical Room	Miscellaneous	Mineral Particulate / Rock Wool	1 other	Good	No	Yes	No	GM020019		NA	07/03/05 : TBD
104	Interior	1	n/a	Mechanical Room	Miscellaneous	Mineral Particulate / Rock Wool	1 other	Good	No	Yes	No	GM020018		NA	07/03/05 : TBD
104	Interior	1	N/A	Utility Room	TSI	Insulation, tank/pipe	45 Linear Feet	Good	Yes	No	No			20	11/06/02 : TBD
104	Interior	1	N/A	Utility Room	Surfacing	Cementitious, troweled-on, surfacing	100 Square Feet	Good	No	No	No			5	11/06/04 : TBD
104	Interior	1	N/A	Utility Room	TSI	gasket		Good	No	Yes	No	0007981-001		5	11/06/04 : TBD
104	Interior	1st	N/A	vehicle dispatch	Surfacing	Floor tile adhesive	1 other	Good	No	Yes	No	GM020081		NA	01/14/06 : TBD
104	Interior	1st	N/A	vehicle dispatch	Surfacing	Floor Adhesive	1 other	Good	No	Yes	No	GM020082		NA	06/03/06 : TBD
107	Interior	1	Kitchen	Kitchen	Surfacing	Kettle Piping	1 other	Good	No	Yes	No	GM030062		NA	06/16/06 : TBD
107	Interior	1	N/A	Mechanical Room	TSI	Condensate Return piping	20 Linear Feet	Good	No	Yes	No	0007981-47		NA	02/28/06 : TBD
107	Interior	1	N/A	Mechanical Room	TSI	cold water joints	5 each	Good	No	Yes	No	0007981-48		NA	02/28/06 : TBD
107	Interior	1	N/A	Mechanical Room	TSI	return line joints	5 each	Good	Yes	Yes	No	0007981-49		NA	02/28/04 : TBD
110	Exterior	Roof	n/a	Roof	Surfacing	Asphaltic Material / Mineral Particulate	1 other	Good	No	Yes	No	02829-110A		NA	09/03/05 : TBD
111	Interior	1	N/A	SE Mechanical Room	TSI	Hot Water Piping - white heat exchanger/coverer covering	3 Linear Feet	Good	Yes	Yes	Yes	0007981-50		NA	02/28/04 : TBD
111	Interior	1	N/A	SE Mechanical Room	TSI	heat exchanger/coverer covering	10 Square Feet	Good	Yes	Yes	No	0007981-51		NA	02/28/04 : TBD
111	Interior	1	N/A	Utility Room	Miscellaneous	Caulk, ceiling joint		Good	No	Yes	Yes	GMARS11070-1-111-10		10	11/07/04 : TBD
111	Interior	1	N/A	Utility Room	TSI	Insulation, tank/pipe	45 Linear Feet	Good	Yes	Yes	No	GMARS11070-1-111-09		10	11/07/02 : TBD
111	Interior	1	N/A	Utility Room	TSI	Insulation, pipe	3 Linear Feet	Good	Yes	No	Yes			10	11/07/02 : TBD
111	Interior	1	N/A	Utility Room	TSI	Gasket		Good	No	No	No			2	11/07/04 : TBD
111	Interior	1	N/A	Utility Room	Surfacing	Black substance on ceiling	1 Square Feet	Good	No	No	No			2	11/07/04 : TBD
111	Exterior	Roof	n/a	Roof	Surfacing	Asphaltic Material / Mineral Particulate	1 other	Good	No	Yes	No	02829-111B		NA	09/03/05 : TBD
111	Exterior	Roof	n/a	Roof	Surfacing	Asphaltic Material / Mineral Particulate	1 other	Good	No	Yes	No	02829-111A		NA	09/03/05 : TBD
205A	Interior	1	115A	Mechanical Room	TSI	High pressure steam piping	50 Linear Feet	Good	No	Yes	No	0007981-03, 0007981-04		NA	01/16/06 : TBD
205A	Interior	1	115A	Mechanical Room	TSI	condensate line piping	50 Linear Feet	Good	No	Yes	No	0007981-005		NA	01/12/06 : TBD
205A	Interior	1	Interior	Break Room Washroom	TSI	heating system piping	15 Linear Feet	Good	No	Yes	No	0007981-007		NA	01/12/06 : TBD
205A	Interior	1	N/A	Center Washroom	TSI	heating system piping	12 Linear Feet	Good	No	Yes	No	0007981-006		NA	01/12/06 : TBD
205C	Interior	1	102	N/A	Surfacing	Floor Tile	340 Square Feet	Good	No	Yes	Yes	GM030054		NA	06/09/06 : TBD
205C	Interior	1	102	N/A	Surfacing	Carpet Adhesive(2)	1 other	Good	No	Yes	No	GM030055		NA	06/09/06 : TBD
205C	Interior	1	102	N/A	Surfacing	Carpet Adhesive	1 other	Good	No	Yes	No	GM030053		NA	06/06/06 : TBD
205C	Interior	1	102	N/A	Surfacing	Carpet Adhesive	1 other	Good	No	No	No			NA	06/09/06 : TBD
205C	Interior	1	N/A	SATO TRAVEL OFFICE	TSI	Heating Piping - Janitor Closet	20 Linear Feet	Good	No	Yes	No	0007981-14		NA	02/27/06 : TBD

205C	Interior	1	N/A	SATO TRAVEL OFFICE	TSI	heating system piping	15 Linear Feet	Good	No	Yes	No	No		007981-15	NA	02/27/06 : TBD
205D	Interior	1	N/A	West Center Hall	TSI	low pressure condensate line	40 Linear Feet	Good	No	Yes	No	No		0007981-10/11	NA	01/12/06 : TBD
205D	Interior	1	N/A	West Center Hall	TSI	Steam line	80 Linear Feet	Good	No	Yes	No	No		0007981-12/13	NA	01/12/16 : TBD
205D	Interior	1	NW Mech Room	Mech Room	Other	Trap Pipe		Good	No	Yes	Yes	No		GM020001	NA	03/28/06 : TBD
205D	Interior	1	NW Mech Room	Mech Room	Other	LIT Pump Condensation Line		Good	No	Yes	Yes	No		GM020002	NA	03/28/05 : TBD
205D	Interior	1	NW Mech Room	Mech Room	TSI	total 62 pipe fittings	62 each	Good	Yes	No	Yes				NA	10/21/06 : TBD
205E	Interior	N/A	N/A	weapons storage	TSI	steam line piping	25 Linear Feet	Good	No	Yes	No	No		0007981-008	NA	01/12/06 : TBD
205E	Interior	N/A	N/A	weapons storage	TSI	Condensor Line	25 Linear Feet	Good	No	Yes	No	No		007981-009	NA	01/12/06 : TBD
208	Interior	1	Break Room	Break Room	Miscellaneous	Floor tile	1 other	Good	No	Yes	No	No		GM030149	NA	10/23/06 : TBD
208	Interior	1	N/A	Mechanical Room	TSI	Insulations on Fiberglass Water Heating Line	17 each	Good	Yes	No	Yes				NA	09/01/05 : TBD
210 - 212	Exterior	Underground	Ug.	Pipe Area	Surfacing	Insulation	1 other	Good	No	Yes	No	Yes		GM870089	NA	04/21/90 : TBD
210 - 212	Exterior	Underground	Ug.	Pipe Area	Other	Insulation1	1 each	Good	No	Yes	No	Yes		GM870090	NA	04/21/90 : TBD
212	Interior	1	N/A	Mechanical Room	TSI	hot water return line	30 Linear Feet	Good	No	Yes	No	No		0007981-18	NA	02/28/06 : TBD
212	Interior	1	N/A	Mechanical Room	TSI	cold water line	35 Linear Feet	Good	No	Yes	No	Yes		0007981-19	NA	02/28/06 : TBD
212	Interior	1	N/A	Mechanical Room	TSI	low pressure condensate - brown	40 Linear Feet	Good	No	Yes	No	No		0007981-20	NA	02/28/06 : TBD
212	Interior	1	N/A	Mechanical Room	TSI	Exchanger hot water inlet	2 Linear Feet	Good	Yes	Yes	No	No		0007981-21	NA	02/28/04 : TBD
212	Interior	1	N/A	Mechanical Room	TSI	condenser pipe	40 Linear Feet	Good	No	Yes	No	No		0007981-22	NA	02/28/06 : TBD
212	Interior	1	N/A	Mechanical Room	TSI	low pressure steam line - orange	30 Linear Feet	Good	No	Yes	No	Yes		0007981-23	NA	02/28/06 : TBD
212	Interior	1	N/A	Mechanical Room	TSI	insulation on fiberglass domestic waterline	20 each	Good	Yes	No	Yes				NA	09/01/05 : TBD
212	Interior	1	Stall 1	N/A	TSI	Heater Piping	50 Linear Feet	Good	No	Yes	No	Yes		0007981-16	NA	02/27/06 : TBD
212	Interior	1	Stall 1	N/A	TSI	Heater piping joints	4 each	Good	No	Yes	No	Yes		0007981-17	NA	02/27/06 : TBD
212	Exterior	Roof	n/a	Roof	Surfacing	Asphaltic Material / Glass Wool / Mineral Particulate	1 other	Good	No	Yes	No	No		02829-212A	NA	09/03/05 : TBD
217	Interior	1	103	Small Paint Booth Area	TSI	Insulation, pipe, black	15 Linear Feet	Good	No	No	No				12	11/05/04 : TBD
217	Interior	1	104	Floor	Miscellaneous	Tile, white 12x12	756 Square Feet	Good	No	No	No				NA	11/05/04 : TBD
217	Interior	1	104	Floor	Miscellaneous	Mastic	756 Square Feet	Good	No	No	No				1	11/05/04 : TBD
217	Interior	1	104	Floor	Miscellaneous	Tile, white 12x12	756 Square Feet	Good	No	No	No				6	11/05/04 : TBD
217	Interior	1	106	Breakroom	TSI	Covering, insulation	69 Linear Feet	Good	No	No	No				12	11/05/04 : TBD
217	Interior	1	106	Breakroom	TSI	lower level piping	50 Linear Feet	Good	No	Yes	No	No		0007981-37	NA	02/28/06 : TBD
217	Interior	1	106	Breakroom	TSI	Upper piping	50 Linear Feet	Good	Yes	Yes	No	Yes		0007981-38	NA	02/28/04 : TBD
217	Interior	1	106	Breakroom	TSI	Upper Piping Elbows	8 each	Good	Yes	Yes	No	Yes		0007981-39	NA	02/28/04 : TBD
217	Interior	1	106	Hallway and Breakroom	TSI	heater piping - hallway	15 Linear Feet	Good	No	Yes	No	No		0007981-33	NA	02/28/06 : TBD
217	Interior	1	106	Hallway and Breakroom	Miscellaneous	Floor Tile, Purple	3404 Square Feet	Good	No	Yes	No	No		GMARS110501-217-01	6	11/05/04 : TBD
217	Interior	1	109	Hallway and Breakroom	Miscellaneous	Floor Tile, Purple	3404 Square Feet	Good	No	Yes	No	No		GMARS110501-217-01	6	11/05/04 : TBD
217	Interior	1	109	Hallway and Breakroom	TSI	heater piping stairwell	20 Linear Feet	Good	No	Yes	No	No		0007981-40	NA	02/28/06 : TBD
217	Interior	1	112	Floor	Miscellaneous	Tile, floor, grey white, 12x12	1512 Square Feet	Good	No	No	No				6	11/05/04 : TBD
217	Interior	1	112	N/A	TSI	Insulation, pipe	360 Linear Feet	Good	Yes	No	No				24	11/05/02 : TBD
217	Interior	1	112	N/A	Miscellaneous	Panel, transite	84 Square Feet	Good	No	No	No				24	11/05/04 : TBD
217	Interior	1	121	hangar	TSI	Covering, pipe insulation	95 Linear Feet	Good	No	Yes	No	No		GMARS110701-217-04	10	11/05/04 : TBD
217	Interior	1	122	hangar	TSI	Covering, pipe insulation	95 Linear Feet	Good	No	Yes	No	No		GMARS110701-217-04	10	11/05/04 : TBD
217	Interior	1	124	Floor	Miscellaneous	Mastic	756 Square Feet	Good	No	No	No				1	11/05/04 : TBD
217	Interior	1	124	hangar	TSI	Supervisor Office Piping	8 Linear Feet	Fair	Yes	No	Yes				NA	12/03/03 : Removed
217	Interior	1	124	hangar	TSI	Covering, pipe insulation	95 Linear Feet	Good	No	Yes	No	No		GMARS110701-217-04	10	11/05/04 : TBD
217	Interior	1	125	hangar	TSI	Covering, pipe insulation	95 Linear Feet	Good	No	Yes	No	No		GMARS110701-217-04	10	11/05/04 : TBD

217	Interior	1	N/A	Classroom, East Side of Hangar	Miscellaneous	Tile, floor, beige, 12x12		Good	No	No	No			6	11/05/04 : TBD
217	Interior	1	N/A	Electrical Shop Break Room	TSI	heater piping	15 Linear Feet	Good	No	Yes	No	No	0007981-34	NA	02/28/06 : TBD
217	Interior	1	N/A	Hall Z21, East Side of Hangar	Miscellaneous	Tile, floor, beige, 12x12		Good	No	No	No			6	11/05/04 : TBD
217	Interior	1	N/A	Main Hangar	TSI	Insulation, pipe		Good	Yes	No	No			NA	11/05/02 : TBD
217	Interior	1	N/A	Main Hangar	TSI	Covering, pipe insulation	95 Linear Feet	Good	No	Yes	No	No	GMARS11070 1-217-04	10	11/05/04 : TBD
217	Interior	1	N/A	Main Hangar SE Wash Rack	TSI	Cold Water Piping	40 Linear Feet	Good	No	Yes	No	Yes	0007981-25	NA	02/28/06 : TBD
217	Interior	1	N/A	Main Hangar SE Wash Rack	TSI	condensator piping along ceiling	50 Linear Feet	Good	No	Yes	No	No	0007981-26	NA	02/28/06 : TBD
217	Interior	1	N/A	Main Hangar SE Wash Rack	TSI	Steam piping along ceiling	50 Linear Feet	Good	No	Yes	No	No	0007981-27	NA	02/28/06 : TBD
217	Interior	1	N/A	Stairwell, East Side of Hangar	TSI	Heater Piping	15 Linear Feet	Good	No	Yes	No	No	0007981-24	NA	02/28/06 : TBD
217	Interior	1	N/A	Stairwell, East Side of Hangar	Surfacing	Black Runner	1 other	Good	No	Yes	No	No	GM030058	NA	06/06/06 : TBD
217	Interior	1	N/A	Stairwell, East Side of Hangar	Surfacing	Runner Adhesive	1 other	Good	No	Yes	No	Yes	GM030059	NA	06/06/06 : TBD
217	Interior	1	N/A	Stairwell, East Side of Hangar	Surfacing	Brown Runner	1 other	Good	No	Yes	No	No	GM030060	NA	06/06/06 : TBD
217	Interior	1	N/A	Stairwell, East Side of Hangar	Miscellaneous	Tile, floor, beige, 12x12		Good	No	No	No			6	11/05/04 : TBD
217	Interior	1	N/A	Welding Shop	TSI	heater piping - 4"	25 Linear Feet	Good	No	Yes	No	No	0007981-35	NA	02/28/06 : TBD
217	Interior	1	N/A	Welding Shop	TSI	heater piping - 6"	25 Linear Feet	Good	No	Yes	No	No	0007981-36	NA	02/28/06 : TBD
217	Interior	1	N/A	West Entrance	TSI	elbows adjacent to radiator	3 each	Fair	Yes	No	Yes			NA	12/03/03 : Removed
217	Interior	1	N/A	West Main Hangar	TSI	Insulation, pipe	650 Linear Feet	Good	Yes	No	No			24	11/05/02 : TBD
217	Interior	1	Outside 118	Stairwell	Miscellaneous	Tile, floor, tan 12x12	5 Square Feet	Good	No	No	No			6	11/05/04 : TBD
217	Interior	2	207	Auditorium Mechanical Room	TSI	heater insulation	30 Linear Feet	Good	No	Yes	No	No	0007981-30	NA	02/28/06 : TBD
217	Interior	2	207	Auditorium Mechanical Room	TSI	heater piping joint compound	4 each	Good	Yes	Yes	No	Yes	0007981-31	NA	02/28/04 : TBD
217	Interior	2	208	N/A	Miscellaneous	mastic		Good	No	No	No			6	11/05/04 : TBD
217	Interior	2	208	Office	Miscellaneous	Tile, ceiling, patterned, 9x9	300 Square Feet	Good	Yes	Yes	No	Yes	GMARS11070 1-217-05	36	11/05/02 : TBD
217	Interior	2	208	Office	Miscellaneous	Tile, ceiling, white dotted, 12x12	1 Square Feet	Good	Yes	Yes	No	No	GMARS11070 1-217-06	12	11/05/02 : TBD
217	Interior	2	211	N/A	TSI	Insulation, pipe	30 Linear Feet	Good	No	No	No			24	11/05/04 : TBD
217	Interior	2	N/A	Hall Doorway	Miscellaneous	panel	4 Square Feet	Good	No	No	No			6	11/05/04 : TBD
217	Interior	2	N/A	Hall Floor, 2nd deck	Miscellaneous	Tile, floor, brown, 9x9		Good	No	No	No			12	11/05/04 : TBD
217	Interior	2	N/A	Hallway	TSI	elbows adjacent to Radiators	23 each	Fair	Yes	No	Yes			NA	12/03/03 : Removed
217	Interior	2	N/A	Men's Room	TSI	Insulation	3 Linear Feet	Good	Yes	No	No			12	11/05/02 : TBD
217	Interior	N/A	1005	N/A	Miscellaneous	Floor tile (maroon colored)	1 Linear Feet	Good	No	Yes	No	No	GM030114	NA	10/24/06 : TBD
217	Interior	N/A	1008	N/A	Miscellaneous	Floor tile (green 2 shades)	1 other	Good	No	Yes	No	Yes	GM030120	NA	10/24/06 : TBD
217	Interior	N/A	2040	N/A	Miscellaneous	Floor tile w/black mastic	1 other	Good	No	Yes	No	Yes	GM030019	NA	10/24/06 : TBD
217	Interior	N/A	2041	N/A	Miscellaneous	Floor tile (flesh colored)	1 other	Good	No	Yes	No	Yes	GM030018	NA	10/24/06 : TBD
217	Interior	N/A	2042	N/A	Miscellaneous	Floor tile (flesh colored)	1 other	Good	No	Yes	No	Yes	GM030017	NA	10/24/06 : TBD
217	Interior	N/A	2047	N/A	Miscellaneous	Floor tile (bone colored)	1 other	Good	No	Yes	No	Yes	GM030116	NA	10/24/06 : TBD
217	Interior	N/A	2048	N/A	Miscellaneous	Floor tile (bone colored)	1 other	Good	No	Yes	No	Yes	GM030115	NA	10/24/06 : TBD
217	Interior	N/A	N/A	Center Stairs Between floors	TSI	heater piping	10 Linear Feet	Good	No	Yes	No	No	0007981-32	NA	02/28/06 : TBD
217	Interior	N/A	N/A	SE Stairwell	Surfacing	Beige Floor Tile	1 other	Good	No	Yes	No	Yes	GM030056	NA	06/06/06 : TBD
217	Interior	N/A	N/A	SE Stairwell	Surfacing	Tile Adhesive	1 other	Good	No	Yes	No	Yes	GM030057	NA	06/06/06 : TBD
218	Interior	1	107	OUTSIDE 107	Other	Test	1 other	Good	No	Yes	No	No		1	06/03/06 : TBD
218	Interior	1	N/A	Mechanical Room	Other	Pipe insulation- asphalt wrap	2 Linear Feet	Fair	No	Yes	Yes	No	GM030042	NA	05/27/06 : TBD
219	Interior	1	N/A	Central Shop Area	TSI	condensate piping	60 Linear Feet	Good	No	Yes	No	No	007981-41	NA	02/28/06 : TBD
219	Interior	1	N/A	Central Shop Area	TSI	steam piping	60 Linear Feet	Good	No	Yes	No	No	007981-42	NA	02/28/06 : TBD
219	Interior	1	N/A	Central Shop Area	TSI	pipe wrapping joints	15 each	Good	No	Yes	No	No	0007981-43	NA	02/28/06 : TBD
219	Interior	1	N/A	Mechanical Room	TSI	condensate piping - brown	20 Linear Feet	Good	No	Yes	No	No	0007981-44	NA	02/28/06 : TBD

219	Interior	1	N/A	Mechanical Room	TSI	high pressure steam line - orange	20 Linear Feet	Good	No	Yes	No	No		0007981-45	NA	02/28/06 : TBD
219	Interior	1	N/A	Mechanical Room	TSI	condensate return - white	20 Linear Feet	Good	No	Yes	No	No		0007981-46	NA	02/28/06 : TBD
222	Interior	1	103	office	Surfacing	Tile	1 other	Good	No	Yes	No	No		GMAF2330	NA	11/26/05 : TBD
222	Interior	1	103	office	Surfacing	Carpet	1 Square Feet	Good	No	Yes	No	No		GMAF2330	NA	11/26/05 : TBD
222	Interior	1	103	office	Surfacing	adhesive flooring	1 other	Good	No	Yes	No	No		GMAF2330	NA	11/26/05 : TBD
222	Interior	1	103	office	Surfacing	Floor tile	1 other	Good	No	Yes	No	No		GM020058	NA	12/05/05 : TBD
222	Interior	1	103	office	Surfacing	Carpeting	1 other	Good	No	Yes	No	No		GM020059	NA	12/05/06 : TBD
222	Interior	1	103	office	Surfacing	Mastic	1 other	Good	No	Yes	No	No		GM020060	NA	12/05/06 : TBD
300	Interior	1	N/A	Bathroom	Miscellaneous	Tile, floor, beige, 12x12	45 Square Feet	Good	No	Yes	No	Yes		GMARS11070 1-300-08	16	11/07/04 : TBD
300	Interior	1	N/A	Classroom	Miscellaneous	Glazing, window		Good	No	Yes	No	Yes		GMARS11070 1-300-07	10	11/07/04 : TBD
302	Interior	1	N/A	MECHANICAL ROOM	TSI	fiberglass insulated heating, domestic cold/hot waterline & capping insulation	203 each	Good	Yes	No	Yes				NA	09/01/05 : TBD
303	Exterior	Roof	N/A	Roof	Surfacing	Flashing-1	1 each	Good	No	Yes	No	No		03-010903A	NA	01/10/06 : TBD
303	Exterior	Roof	N/A	Roof	Surfacing	Flashing-2	1 other	Good	No	Yes	No	Yes		03-010903B	NA	01/10/06 : TBD
303	Exterior	Roof	N/A	Roof	Surfacing	Roofing	1 other	Good	No	Yes	No	No		03-010903C	NA	01/10/06 : TBD
303	Exterior	Roof	N/A	Roof	Surfacing	Roofing-2	1 other	Good	No	Yes	No	No		03-010903D	NA	01/10/06 : TBD
304	Interior	1	Main	55 gal drum	Other	Fitting Repair Dry Cement Mix		Good	Yes	Yes	No	No		GM020055	NA	11/03/11 : TBD
304	Interior	1	N/A	Office Area	Miscellaneous	Floor Tile	1 Linear Feet	Good	No	Yes	No	No		GM030152	NA	10/23/06 : TBD
305	Interior	1	Interior	all rooms	Miscellaneous	Mastic	1 other	Good	No	Yes	No	No		GM030151	NA	10/23/06 : TBD
305	Interior	1	Interior	N/A	Miscellaneous	Floor Tile	1 Linear Feet	Good	No	Yes	No	No		GM030150	NA	10/23/06 : TBD